# Water Sampling Log

Name of Building (see below)
Building Owner Washington Township Bd of Educ

Date Collected 17-Dec-21
Collected by AR Simon

| Sample No. | Tap No. | Sample Type | Type of Outlet | Manufacturer | Location | Time | Results (µg/L) | |
|---|---|---|---|---|---|---|---|---|
| | | | | | | | Cu | Pb |
| | | | | | | | | |
| | | | | | **Brass Castle School** | | | |
| RK-121721-01 | **1** | 1st | Bubbler | | Main Hallway - across from Main Office | 07:32 | XX | < 1.0 |
| RK-121721-02 | **6a** | 1st | Bubbler | | Nurse's Office, left side | 07:34 | XX | 1.1 |
| RK-121721-03 | **6b** | 1st | Bubbler | | Nurse's Office, right side | 07:35 | XX | 5.0 |
| RK-121721-04 | **12** | 1st | Sink | | Kitchen | 07:42 | XX | < 1.0 |
| RK-121721-05 | **13** | 1st | Hose Filler | | Kitchen - Spray Hose | 07:44 | XX | 6.9 |
| RK-121721-06 | **15** | 1st | Sink | | Faculty Room 211 | 07:48 | XX | < 1.0 |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | **Port Colden School** | | | |
| RK-121721-07 | **1** | 1st | Sink | | Kitchen | 08:16 | XX | 3.5 |
| RK-121721-08 | **2** | 1st | Hose | | Kitchen | 08:17 | XX | 5.9 |
| RK-121721-09 | **3** | 1st | Sink | | Nurse's Office - bathroom sink, east side | 08:14 | XX | < 1.0 |
| RK-121721-10 | **10** | 1st | Fountain | | Main Hallway - outside of Room 200 | 08:08 | XX | < 1.0 |
| RK-121721-11 | **11** | 1st | Sink | | Main Hallway - Faculty lav, across from Main Office | 08:10 | XX | 2.4 |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

Sample Type: 1st: First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
**<: means** Not Detected at or above the Reliability Detection Limit (RDL) of 0.0010 mg/L for Lead.